

FIG. 1








FIG.2a**FIG.2b****FIG.2c****FIG.2d**START OF
LUBRICATIONAPPLICATION
OF PRESSURECOMPLETION
OF DISCHARGE

MEASUREMENT

FIG. 3




FIG. 4




FIG. 5




FIG.6a




FIG.6b




FIG.6c





FIG.6d




FIG. 7




FIG. 8




FIG. 9




FIG.10

